



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

February 25, 2005

RE: FCC ID: QTKRM-72_ATCB002172
Attention: Stephan Emery

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that while I find the Block diagram of the GSM portion, I could not find the BT block diagram. Please provide the BT block diagram or alternately, please point to the portion of the Block diagram dealing with the BT transmitter section.
2. Please note that the setup diagram on page 4 of test report QTKRM-72_Exhibit 6_0504_02_v01.pdf is blackened out and indiscernible. Please provide a setup drawing that can be clearly seen.
3. Please note that the data tables in the report "QTKRM-72_Exhibit 6_0504_06_v01.pdf" are missing the value U_{rx} as stated in the formula (see pages 11 and 12 of the specified report). Please provide this information in the tables.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.