

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. 25b Emissions Requirement

MKR 3.22 KHz

Report No.: 0408440

Model No.: 8226


REF 10.0 dBm

AT 20 dB

-7.10 dB

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By: *[Signature]*
(Cory Li)

Date: 3-6-04

Checked By: *[Signature]*
(Ivan Wong)

Date: 3-7-04

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 3.0 KHz

VBW 3 KHz

STOP 13.56700 MHz

#SWP 10.0 sec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15.225C Emissions Requirement

MKR -153.8 KHz

Report No.: 040940

Model No.: 8226

REF 10.0 dBm

AT 20 dB

-43.18 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By:

Date: 3-6-04

Checked By:

(Ivan Wong)

Date:

3/7/04

Test Result: Pass / Fail / NA

START 13.4100 MHz

#RES BW 3.0 KHz

VBW 3 KHz

STOP 13.7100 MHz

#SWP 10.0 sec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. 225d Emissions Requirement

MKR 443.3 KHz

Report No.: 0408440

Model No.: 8226


REF 10.0 dBm

AT 20 dB

-53.48 dB

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By:

(Gang Li)

Date:

3/6/04

Checked By:

(Anthony Chan)

Date:

7/6/04

Test Result : Pass / Fail / NA

START 13.1100 MHz

STOP 14.0100 MHz

#RES BW 3.0 KHz

VBW 3 KHz

#SWP 10.0 sec