




802.11ac(VHT80)_MCH_5210MHz_Ant1_NTNV




802.11ac(VHT80)_MCH_5210MHz_Ant5_NTNV



802.11ac(VHT80)_MCH_5290MHz_Ant1_NTNV



802.11ac(VHT80)_MCH_5290MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 418 of 807


802.11ac(VHT80)_LCH_5530MHz_Ant1_NTNV




802.11ac(VHT80)_LCH_5530MHz_Ant5_NTNV




802.11ac(VHT80)_HCH_5610MHz_Ant1_NTNV




802.11ac(VHT80)_HCH_5610MHz_Ant5_NTNV




802.11ac(VHT80)_MCH_5775MHz_Ant1_NTNV




802.11ac(VHT80)_MCH_5775MHz_Ant5_NTNV




802.11ac(VHT160)_MCH_5570MHz_Ant1_NTNV




802.11ac(VHT160)_MCH_5570MHz_Ant5_NTNV




802.11ac(VHT160)_MCH_5250MHz_Ant1_NTNV




802.11ac(VHT160)_MCH_5250MHz_Ant5_NTNV




802.11ax(HEW20)_LCH_5180MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5180MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5200MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5200MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5240MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5240MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_LCH_5260MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5260MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5300MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5300MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5320MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5320MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_LCH_5500MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5500MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5580MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5580MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5700MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5700MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_LCH_5745MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5745MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5785MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5785MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5825MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5825MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5190MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_5190MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_5230MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5230MHz_RU484_Left_Ant5_NTNV



802.11ax(HEW40)_LCH_5270MHz_RU484_Left_Ant1_NTNV



802.11ax(HEW40)_LCH_5270MHz_RU484_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 438 of 807


802.11ax(HEW40)_HCH_5310MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5310MHz_RU484_Left_Ant5_NTNV



802.11ax(HEW40)_LCH_5510MHz_RU484_Left_Ant1_NTNV



802.11ax(HEW40)_LCH_5510MHz_RU484_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 440 of 807


802.11ax(HEW40)_MCH_5550MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_5550MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_5670MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5670MHz_RU484_Left_Ant5_NTNV



802.11ax(HEW40)_LCH_5755MHz_RU484_Left_Ant1_NTNV



802.11ax(HEW40)_LCH_5755MHz_RU484_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 443 of 807


802.11ax(HEW40)_HCH_5795MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5795MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW80)_MCH_5210MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_5210MHz_RU996_Left_Ant5_NTNV



802.11ax(HEW80)_MCH_5290MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_MCH_5290MHz_RU996_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 446 of 807


802.11ax(HEW80)_LCH_5530MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_5530MHz_RU996_Left_Ant5_NTNV



802.11ax(HEW80)_HCH_5610MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_HCH_5610MHz_RU996_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 448 of 807

802.11ax(HEW80)_MCH_5775MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_MCH_5775MHz_RU996_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 449 of 807


802.11ax(HEW160)_MCH_5570MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_5570MHz_2xRU996_Left_Ant5_NTNV




802.11ax(HEW160)_MCH_5250MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_5250MHz_2xRU996_Left_Ant5_NTNV




2.2.2 6dB BW




802.11a_MCH_5785MHz_Ant1_NTNV




802.11a_MCH_5785MHz_Ant5_NTNV




802.11a_HCH_5825MHz_Ant1_NTNV




802.11a_HCH_5825MHz_Ant5_NTNV




802.11n(HT20)_LCH_5745MHz_Ant1_NTNV




802.11n(HT20)_LCH_5745MHz_Ant5_NTNV



802.11n(HT20)_MCH_5785MHz_Ant1_NTNV



802.11n(HT20)_MCH_5785MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 456 of 807


802.11n(HT20)_HCH_5825MHz_Ant1_NTNV




802.11n(HT20)_HCH_5825MHz_Ant5_NTNV




802.11n(HT40)_LCH_5755MHz_Ant1_NTNV




802.11n(HT40)_LCH_5755MHz_Ant5_NTNV




802.11n(HT40)_HCH_5795MHz_Ant1_NTNV




802.11n(HT40)_HCH_5795MHz_Ant5_NTNV



802.11ac(VHT20)_LCH_5745MHz_Ant1_NTNV



802.11ac(VHT20)_LCH_5745MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 460 of 807

802.11ac(VHT20)_MCH_5785MHz_Ant1_NTNV



802.11ac(VHT20)_MCH_5785MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 461 of 807


802.11ac(VHT20)_HCH_5825MHz_Ant1_NTNV




802.11ac(VHT20)_HCH_5825MHz_Ant5_NTNV




802.11ac(VHT40)_LCH_5755MHz_Ant1_NTNV




802.11ac(VHT40)_LCH_5755MHz_Ant5_NTNV




802.11ac(VHT40)_HCH_5795MHz_Ant1_NTNV




802.11ac(VHT40)_HCH_5795MHz_Ant5_NTNV




802.11ac(VHT80)_MCH_5775MHz_Ant1_NTNV




802.11ac(VHT80)_MCH_5775MHz_Ant5_NTNV




802.11ax(HEW20)_LCH_5745MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5745MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5785MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5785MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5825MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5825MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5755MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_5755MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_5795MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5795MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW80)_MCH_5775MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_5775MHz_RU996_Left_Ant5_NTNV




2.2.3 26dB BW




802.11a_MCH_5200MHz_Ant1_NTNV




802.11a_MCH_5200MHz_Ant5_NTNV




802.11a_HCH_5240MHz_Ant1_NTNV




802.11a_HCH_5240MHz_Ant5_NTNV



802.11a_LCH_5260MHz_Ant1_NTNV



802.11a_LCH_5260MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 475 of 807


802.11a_MCH_5300MHz_Ant1_NTNV




802.11a_MCH_5300MHz_Ant5_NTNV




802.11a_HCH_5320MHz_Ant1_NTNV




802.11a_HCH_5320MHz_Ant5_NTNV




802.11a_LCH_5500MHz_Ant1_NTNV




802.11a_LCH_5500MHz_Ant5_NTNV




802.11a_MCH_5580MHz_Ant1_NTNV




802.11a_MCH_5580MHz_Ant5_NTNV




802.11a_HCH_5700MHz_Ant1_NTNV




802.11a_HCH_5700MHz_Ant5_NTNV



802.11n(HT20)_LCH_5180MHz_Ant1_NTNV



802.11n(HT20)_LCH_5180MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 481 of 807


802.11n(HT20)_MCH_5200MHz_Ant1_NTNV




802.11n(HT20)_MCH_5200MHz_Ant5_NTNV




802.11n(HT20)_HCH_5240MHz_Ant1_NTNV




802.11n(HT20)_HCH_5240MHz_Ant5_NTNV




802.11n(HT20)_LCH_5260MHz_Ant1_NTNV




802.11n(HT20)_LCH_5260MHz_Ant5_NTNV




802.11n(HT20)_MCH_5300MHz_Ant1_NTNV




802.11n(HT20)_MCH_5300MHz_Ant5_NTNV




802.11n(HT20)_HCH_5320MHz_Ant1_NTNV




802.11n(HT20)_HCH_5320MHz_Ant5_NTNV




802.11n(HT20)_LCH_5500MHz_Ant1_NTNV




802.11n(HT20)_LCH_5500MHz_Ant5_NTNV




802.11n(HT20)_MCH_5580MHz_Ant1_NTNV




802.11n(HT20)_MCH_5580MHz_Ant5_NTNV




802.11n(HT20)_HCH_5700MHz_Ant1_NTNV




802.11n(HT20)_HCH_5700MHz_Ant5_NTNV



802.11n(HT40)_LCH_5190MHz_Ant1_NTNV



802.11n(HT40)_LCH_5190MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 490 of 807


802.11n(HT40)_HCH_5230MHz_Ant1_NTNV




802.11n(HT40)_HCH_5230MHz_Ant5_NTNV




802.11n(HT40)_LCH_5270MHz_Ant1_NTNV




802.11n(HT40)_LCH_5270MHz_Ant5_NTNV




802.11n(HT40)_HCH_5310MHz_Ant1_NTNV




802.11n(HT40)_HCH_5310MHz_Ant5_NTNV




802.11n(HT40)_LCH_5510MHz_Ant1_NTNV




802.11n(HT40)_LCH_5510MHz_Ant5_NTNV




802.11n(HT40)_MCH_5550MHz_Ant1_NTNV




802.11n(HT40)_MCH_5550MHz_Ant5_NTNV




802.11n(HT40)_HCH_5670MHz_Ant1_NTNV




802.11n(HT40)_HCH_5670MHz_Ant5_NTNV




802.11ac(VHT20)_LCH_5180MHz_Ant1_NTNV




802.11ac(VHT20)_LCH_5180MHz_Ant5_NTNV




802.11ac(VHT20)_MCH_5200MHz_Ant1_NTNV




802.11ac(VHT20)_MCH_5200MHz_Ant5_NTNV




802.11ac(VHT20)_HCH_5240MHz_Ant1_NTNV




802.11ac(VHT20)_HCH_5240MHz_Ant5_NTNV



802.11ac(VHT20)_LCH_5260MHz_Ant1_NTNV



802.11ac(VHT20)_LCH_5260MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 500 of 807


802.11ac(VHT20)_MCH_5300MHz_Ant1_NTNV




802.11ac(VHT20)_MCH_5300MHz_Ant5_NTNV




802.11ac(VHT20)_HCH_5320MHz_Ant1_NTNV




802.11ac(VHT20)_HCH_5320MHz_Ant5_NTNV




802.11ac(VHT20)_LCH_5500MHz_Ant1_NTNV




802.11ac(VHT20)_LCH_5500MHz_Ant5_NTNV




802.11ac(VHT20)_MCH_5580MHz_Ant1_NTNV




802.11ac(VHT20)_MCH_5580MHz_Ant5_NTNV



802.11ac(VHT20)_HCH_5700MHz_Ant1_NTNV



802.11ac(VHT20)_HCH_5700MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 505 of 807


802.11ac(VHT40)_LCH_5190MHz_Ant1_NTNV




802.11ac(VHT40)_LCH_5190MHz_Ant5_NTNV




802.11ac(VHT40)_HCH_5230MHz_Ant1_NTNV




802.11ac(VHT40)_HCH_5230MHz_Ant5_NTNV



802.11ac(VHT40)_LCH_5270MHz_Ant1_NTNV



802.11ac(VHT40)_LCH_5270MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 508 of 807


802.11ac(VHT40)_HCH_5310MHz_Ant1_NTNV




802.11ac(VHT40)_HCH_5310MHz_Ant5_NTNV




802.11ac(VHT40)_LCH_5510MHz_Ant1_NTNV




802.11ac(VHT40)_LCH_5510MHz_Ant5_NTNV




802.11ac(VHT40)_MCH_5550MHz_Ant1_NTNV




802.11ac(VHT40)_MCH_5550MHz_Ant5_NTNV




802.11ac(VHT40)_HCH_5670MHz_Ant1_NTNV




802.11ac(VHT40)_HCH_5670MHz_Ant5_NTNV




802.11ac(VHT80)_MCH_5210MHz_Ant1_NTNV




802.11ac(VHT80)_MCH_5210MHz_Ant5_NTNV




802.11ac(VHT80)_MCH_5290MHz_Ant1_NTNV




802.11ac(VHT80)_MCH_5290MHz_Ant5_NTNV



802.11ac(VHT80)_LCH_5530MHz_Ant1_NTNV



802.11ac(VHT80)_LCH_5530MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 515 of 807

802.11ac(VHT80)_HCH_5610MHz_Ant1_NTNV



802.11ac(VHT80)_HCH_5610MHz_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 516 of 807


802.11ac(VHT160)_MCH_5570MHz_Ant1_NTNV




802.11ac(VHT160)_MCH_5570MHz_Ant5_NTNV




802.11ac(VHT160)_MCH_5250MHz_Ant1_NTNV




802.11ac(VHT160)_MCH_5250MHz_Ant5_NTNV




802.11ax(HEW20)_LCH_5180MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5180MHz_RU242_Left_Ant5_NTNV



802.11ax(HEW20)_MCH_5200MHz_RU242_Left_Ant1_NTNV



802.11ax(HEW20)_MCH_5200MHz_RU242_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 520 of 807


802.11ax(HEW20)_HCH_5240MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5240MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_LCH_5260MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5260MHz_RU242_Left_Ant5_NTNV



802.11ax(HEW20)_MCH_5300MHz_RU242_Left_Ant1_NTNV



802.11ax(HEW20)_MCH_5300MHz_RU242_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 523 of 807


802.11ax(HEW20)_HCH_5320MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5320MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_LCH_5500MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5500MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_5580MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_5580MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_HCH_5700MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_5700MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5190MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_5190MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_5230MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5230MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5270MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_5270MHz_RU484_Left_Ant5_NTNV



802.11ax(HEW40)_HCH_5310MHz_RU484_Left_Ant1_NTNV



802.11ax(HEW40)_HCH_5310MHz_RU484_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 531 of 807

802.11ax(HEW40)_LCH_5510MHz_RU484_Left_Ant1_NTNV



802.11ax(HEW40)_LCH_5510MHz_RU484_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 532 of 807


802.11ax(HEW40)_MCH_5550MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_5550MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_5670MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_5670MHz_RU484_Left_Ant5_NTNV



802.11ax(HEW80)_MCH_5210MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_MCH_5210MHz_RU996_Left_Ant5_NTNV




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121705

Page: 535 of 807


802.11ax(HEW80)_MCH_5290MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_5290MHz_RU996_Left_Ant5_NTNV




802.11ax(HEW80)_LCH_5530MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_LCH_5530MHz_RU996_Left_Ant5_NTNV



802.11ax(HEW80)_HCH_5610MHz_RU996_Left_Ant1_NTNV



802.11ax(HEW80)_HCH_5610MHz_RU996_Left_Ant5_NTNV

