



FCC ID: RSNFORCE-550

IC ID:

CT Project: p1440011

From: Shawn McMillen

Date: 07/28/2014

1-Please note that the FCC ID on the 731 form is incorrect. Should not contain an additional dash.

DW- Corrected.

2-The plots provided on pages 7 thru 12 in the EMC are very difficult to read. May want to consider reformatting them.

MG – We will try to use a higher resolution next time for the plots. In the interim, people have used the zoom function to view these.

3-Page 3 of the user's manual lists 2 x SC174 10' cables however the picture shows a 20' and 40' cable. Just for noting purposes, no action is necessary.

DW-Notified customer.

4-The table on page 13 of the user's manual lists the maximum gain as being 72dB. Is this correct?

DW-Customer fixed. Revised manual saved.

CT -

Response by:

Submitted by:

Date: