

DATE : November 30, 2016

Nemko Canada Inc
303 River Road
Ottawa, Ontario, Canada
K1V 1H2

Attn: Director of Certification

Statement

The details of products(Model:H756A) are as follows.

- The RF module is located in the controller.
- H756A is DFS client device.
- H756A is the hotspot mode is not available.

By: 

Signature

Tsuda Atsunari

Printed

**Title: General Manager of HMD Business Management Department
Visual Products Operations Division
SEIKO EPSON CORPORATION**

Telephone: +81- 263-87-5881
