

Declaration

Description of the Change

Model : ALV2P
FCC ID : VBU-ALV2P

We, Miwa Lock Co., LTD, located at 3-1-12 Shiba Minato-ku Tokyo Japan, have modified the control board and software in above device.

We have changed the card detection circuit and software for the improvement of stability, but does not alter the device functionality or other characteristics except for the reduction of output power.

Comparison measurements of the card detection circuit were carried out on both the original and modified PCBs and it has been verified that this modification degrades the performance characteristics of the device reported to the Commission at the time of its initial certification. The above comparison consisted of the measurement of radiated emission of fundamental signals from the original and modified PCBs using the same method as in the original test (test report No. EMC14092).

The result of these measurements indicated that the modification degraded the equipment's performance characteristics. The modified equipment also meets the requirements in 47CFR section 15.225 and in other related sections.

Date: July 22th 2014

Katsuyuki Takahashi
Katsuyuki Takahashi
Section Manger
Miwa Lock Co., LTD