








FCC Part 27

LTE Band 4, Normal

1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:50:04

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:50:24

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:50:44

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:52:28

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:52:48

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:53:07

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:53:56

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:54:15

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:54:36

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:56:12

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:56:34

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 09:56:55


LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 10:49:39

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 12:04:45

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:12:56

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 12:06:04

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:14:05

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 10:54:49


LTE Band 38, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




5MHz_High_QPSK_1@0(30MHz~27.2GHz)




10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



10MHz_High_QPSK_1@0(30MHz~27.2GHz)




15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:23:57

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:24:21

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:24:46

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:25:42

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:26:05

20MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 6.DEC.2025 13:26:29


LTE Band 41, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




5MHz_High_QPSK_1@0(30MHz~27.9GHz)




10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



10MHz_High_QPSK_1@0(30MHz~27.9GHz)




15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 17:59:09

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 17:59:32

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 17:59:55

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 18:11:37

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 18:01:15

20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502Z37110E-RF Tester:Permin Fu
Date: 5.DEC.2025 18:09:10

***** END *****