

USB-C

STATUS



ERROR



READY



TRAXXAS

6-CELL

NiMH

2-CELL

LiPo

7-CELL

3-CELL

PEAK DETECTING BALANCE CHARGER

iD



4AMP

USB-C

READ ALL INSTRUCTIONS BEFORE CHARGING

Plug charger into USB-C power FIRST,
then connect the iD battery to charge

Do not charge battery unattended

Input: 5-20V $\text{---} \text{---} \text{---}$ 3A

NiMH: Output: 10.75 V $\text{---} \text{---} \text{---}$ 4A

LiPo: Output: 12.6 V $\text{---} \text{---} \text{---}$ 4A

FCC ID: XVE-TRX1042 MODEL NO. 2985

IC: 8668A-TRX1042 [Traxxas.com/pat](https://www.traxxas.com/pat)



020334017765-10-2023

HKA23081-R00