



Occupied Bandwidth

TM 4 & 2422




Occupied Bandwidth

TM 4 & 2 437



Occupied Bandwidth


TM 4 & 2 452



- Power Supply: 12 V


Occupied Bandwidth

TM 1 & 2 412




Occupied Bandwidth

TM 1 & 2 437




Occupied Bandwidth

TM 1 & 2 462




Occupied Bandwidth

TM 2 & 2 412




Occupied Bandwidth

TM 2 & 2 437




Occupied Bandwidth

TM 2 & 2 462




Occupied Bandwidth

TM 3 & 2 412




Occupied Bandwidth

TM 3 & 2 437




Occupied Bandwidth

TM 3 & 2 462




Occupied Bandwidth

TM 4 & 2422




Occupied Bandwidth

TM 4 & 2 437



Occupied Bandwidth


TM 4 & 2 452




APPENDIX I

Test set up diagrams

▪ Radiated Measurement




▪ Conducted Measurement




Duty Cycle

TM 2 & 2 437 MHz




Duty Cycle

TM 3 & 2 437 MHz



Duty Cycle

TM 4 & 2 437 MHz




APPENDIX III

Unwanted Emissions (Radiated) Test Plot

- Power Supply: 24 V

TM 1 & 2 412 & Z axis & Hor

Detector Mode : PK




TM 1 & 2 412 & Z axis & Hor

Detector Mode : AV



TM 1 & 2 462 & Z axis & Hor

Detector Mode : PK




TM 1 & 2 462 & Z axis & Hor

Detector Mode : AV



TM 2 & 2 412 & Z axis & Hor

Detector Mode : PK




TM 2 & 2 412 & Z axis & Hor

Detector Mode : AV



TM 2 & 2 462 & Z axis & Hor

Detector Mode : PK




TM 2 & 2 462 & Z axis & Hor

Detector Mode : AV




TM 3 & 2 412 & Z axis & Hor

Detector Mode : PK




TM 3 & 2 412 & Z axis & Hor

Detector Mode : AV



TM 3 & 2 462 & Z axis & Hor

Detector Mode : PK




TM 3 & 2 462 & Z axis & Hor

Detector Mode : AV




Detector Mode : PK




TM 4 & 2 452 & Z axis & Hor

Detector Mode : PK




TM 4 & 2 452 & Z axis & Hor

Detector Mode : AV




TM 1 & 2 437 & Y axis & Ver

Detector Mode : AV




TM 2 & 2 462 & Z axis & Hor

Detector Mode : AV




TM 3 & 2 462 & Z axis & Hor

Detector Mode : AV



TM 4 & 2 452 & Z axis & Hor

Detector Mode : AV



- Power Supply: 12 V

TM 1 & 2 437 & Y axis & Ver

Detector Mode : AV

