
APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission




Photo 1



Photo 2

Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical:Z-axis)
Above 1 GHz (Horizontal: Y-axis/ Vertical:X-axis)

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1



Photo 2

End of Report