




































































Tx. Spurious NVNT g 2412MHz Ant2 Ref




Tx. Spurious NVNT g 2412MHz Ant2 Emission








Tx. Spurious NVNT g 2437MHz Ant2 Ref





Tx. Spurious NVNT g 2437MHz Ant2 Emission






































APPENDIX 2-PHOTOS OF TEST SETUP

Note: See test photos in setup photo document for the actual connections between Product and support equipment.

*****END OF THE REPORT*****