
APPENDIX 3: Photographs of Test Setup

Conducted Emission





Photo 1



Photo 2

Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



AE

Precheck of Worst Case Position

Axis X



Antenna 0 deg.



Axis Y



Antenna 90 deg.



Axis Z



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report