


## 6 Photographs of the Test Set-Up

**Photograph 1: Set-up for Co-Located Radiated Spurious Emissions, below 1GHz**



**Photograph 2: Set-up for Co-Located Radiated Spurious Emissions, above 1GHz**



**Prüfbericht - Nr.: CN22RX13 001**  
Test report no.

Seite 23 von 24  
Page 23 of 24

**Photograph 3: Set-up for Conducted Emissions, AC Mains**

