



InterLab[®]

Photo Report on

Test Setups

Report Reference: MDE_SCHMER_1501_FCC_Photo_Setups
Setup photos for test report:
MDE_SCHMER_1501_FCCc

Test Laboratory:
7Layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Note:
The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7 layers GmbH
Borsigstrasse 11
40880 Ratingen, Germany
Phone: +49 (0) 2102 749 0
Fax: +49 (0) 2102 749 350
www.7Layers.com

Aufsichtsratsvorsitzender •
Chairman of the Supervisory Board:
Peter Mertel
Vorstand • Board:
Dr. H. Ansorge

Registergericht • registered in:
Düsseldorf, HRB 44096
USt-IdNr • VAT No.:
DE 203159652
TAX No. 147/5869/0385
A Bureau Veritas Group Company

Safety sensor RSS16-SD-ST8H



Photo 1: Test setup for radiated measurements (Enclosure, below 30 MHz, intentional radiator §15)



Photo 2: Test setup for radiated measurements (Enclosure, semi-anechoic chamber, 30 MHz to 1 GHz, intentional radiator §15)

Safety sensor RSS36-SD-ST



Photo 1: Test setup for radiated measurements (Enclosure, below 30 MHz, intentional radiator §15)




Photo 2: Test setup for radiated measurements (Enclosure, semi-anechoic chamber, 30 MHz to 1 GHz, intentional radiator §15)

Safety sensor RSS260-SD-ST




Photo 1: Test setup for radiated measurements (Enclosure, below 30 MHz, intentional radiator §15)



Photo 2: Test setup for radiated measurements (Enclosure, semi-anechoic chamber, 30 MHz to 1 GHz, intentional radiator §15)