





Appendix G: Conducted Spurious Emission


Test Result

Test Mode	Antenna	Frequency [MHz]	Freq Range [MHz]	Ref Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
11B	Ant1	2412	30~26500	4.93	-42.2	≤ -15.07	PASS
		2437	30~26500	5.26	-42.66	≤ -14.74	PASS
		2462	30~26500	4.49	-42.78	≤ -15.51	PASS
11G	Ant1	2412	30~26500	1.72	-42.14	≤ -18.28	PASS
		2437	30~26500	1.70	-42.99	≤ -18.3	PASS
		2462	30~26500	1.49	-42.38	≤ -18.51	PASS
11N20SISO	Ant1	2412	30~26500	1.60	-41.94	≤ -18.4	PASS
		2437	30~26500	1.37	-42.76	≤ -18.63	PASS
		2462	30~26500	1.72	-42.39	≤ -18.28	PASS

Test Graphs









12. TEST SETUP PHOTO


Conducted Test



Radiated Test (Below 1GHz)




Radiated Test (Above 1GHz)




13. EUT PHOTO

External Photos
M/N: C20



External Photos
M/N: C20



External Photos
M/N: C20




External Photos
M/N: C20




External Photos
M/N: C20



External Photos
M/N: C20



External Photos
M/N: C20



Internal Photos
M/N: C20




Internal Photos
M/N: C20





Internal Photos
M/N: C20





Internal Photos
M/N: C20





Internal Photos
M/N: C20





Internal Photos
M/N: C20



Internal Photos
M/N: C20





Internal Photos
M/N: C20




Internal Photos
M/N: C20



Internal Photos
M/N: C20



Internal Photos
M/N: C20



End of Test Report