












Appendix H: Conducted Spurious Emission Test Result

Test Mode	Antenna	Freq(MHz)	Freq Range [MHz]	Ref Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
DH5	Ant1	2402	30~26500	3.74	-42.2	≤ -16.26	PASS
		2441	30~26500	3.87	-42.67	≤ -16.13	PASS
		2480	30~26500	3.59	-41.78	≤ -16.41	PASS
2DH5	Ant1	2402	30~26500	2.11	-42.33	≤ -17.89	PASS
		2441	30~26500	1.93	-42.6	≤ -18.07	PASS
		2480	30~26500	1.50	-42.68	≤ -18.5	PASS
3DH5	Ant1	2402	30~26500	0.55	-42.07	≤ -19.45	PASS
		2441	30~26500	2.32	-42.77	≤ -17.68	PASS
		2480	30~26500	1.84	-42.05	≤ -18.16	PASS

Test Graphs









14. TEST SETUP PHOTO


Conducted Test



Radiated Test (Below 1GHz)




Radiated Test (Above 1GHz)




15. EUT PHOTO

External Photos
M/N: C20



External Photos
M/N: C20



External Photos
M/N: C20




External Photos
M/N: C20




External Photos
M/N: C20



External Photos
M/N: C20



External Photos
M/N: C20



Internal Photos
M/N: C20




Internal Photos
M/N: C20




Internal Photos
M/N: C20





Internal Photos
M/N: C20





Internal Photos
M/N: C20





Internal Photos
M/N: C20



Internal Photos
M/N: C20





Internal Photos
M/N: C20




Internal Photos
M/N: C20



Internal Photos
M/N: C20



Internal Photos
M/N: C20



End of Test Report