

Appendix 2

Photographs of the Test Configurations

1. Conducted Disturbance
2. Radiated Disturbance

A2-1. Conducted Disturbance

< Mains ports >



A2-2. Radiated Disturbance

< 30 MHz ~ 1 GHz >



< (1 ~ 18) GHz >



Appendix 3

Photographs of EUT

A3-1. EUT

1. Front View of Product




2. Rear View of Product



A3-2. EUT

3. Inside View of Product



Appendix 4

Report Revision History

Revision Date	Description	Revised By	Revision Reviewed By
None	Original	N/A	N/A