



APPENDIX 3: Photographs of test setup



Radiated Spurious Emission

Patch antenna

Below 1 GHz





Above 1 GHz





Monopole antenna

Below 1 GHz





Above 1 GHz





Bow-tie antenna

Below 1 GHz




Above 1 GHz



Worst Case Position


Module
X-axis



Patch antenna
X-axis




Y-axis



Y-axis



Z-axis




Z-axis




Monopole antenna
X-axis




Bow-tie antenna
X-axis




Y-axis



Y-axis



Z-axis



End of Report