Photo Report on

Thermostat
TH-1.1

Test Setups

Report Reference: MDE_Jabil_1703_Photo_Report

Test Laboratory:
7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany

DAkkS
Deutsche
Akkreditierungsstelle
D-PL-12140-01-01

Note:
The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.



Photo 1: Test setup for radiated measurements (below 1 GHz)

Photo 3: Test setup for radiated measurements (below 30 MHz)



Photo 4: Test setup for radiated measurements (30 MHz to 1 GHz)



Photo 5: Test setup for radiated measurements (1 GHz to 26 GHz)