



























Appendix B: Photographs of Test Setup

Product: Soundwin Karaoke, Soundwin

Model: DO-K1

Radiated Emission




Conducted Emission




Appendix C: Photographs of EUT
Product: Soundwin Karaoke, Soundwin
Model: DO-K1
External Photos




















**Product: Soundwin Karaoke, Soundwin
Model: DO-K1
Internal Photos**


































*******END OF REPORT*******