

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1





Photo 2

Worst Case Position

ECU
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



ANT
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



Worst case position



With transponder key inserted (Worst)



Without transponder key inserted

End of Report