

8. PHOTOGRAPHS

Photograph of the Radiated Disturbance Measurements (Maximum emission configuration) – Below 1 GHz

[Front]



[Rear]



Test Report No.: NE2010-F003

211-71 Geumgok Road, Dongtan-myeon, Hwaseong-si, Gyeonggi-do, Republic of Korea
www.nct.re.kr TEL: +82-31-323-6070 FAX : +82-31-323-6071

Page 18 of 22

[Front]



[Rear]

