






Internal Photos



Tested Model: PS100
















Note: The applicant claimed that the antenna on the PCB board is not in use.







Battery 1[#]

Battery 2[#]





ANT






Multiple Model: SP200















Note: The applicant claimed that the antenna on the PCB board is not in use.





Battery 1#



Battery 2#



ANT

