























Conducted RF Spurious Emission


Condition	Mode	Frequency (MHz)	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	1-DH5	2402	-44.18	<=-20	Pass
NVNT	1-DH5	2441	-44.53	<=-20	Pass
NVNT	1-DH5	2480	-43.69	<=-20	Pass
NVNT	2-DH5	2402	-42.3	<=-20	Pass
NVNT	2-DH5	2441	-43.83	<=-20	Pass
NVNT	2-DH5	2480	-41.88	<=-20	Pass
NVNT	3-DH5	2402	-41.72	<=-20	Pass
NVNT	3-DH5	2441	-43.77	<=-20	Pass
NVNT	3-DH5	2480	-41.92	<=-20	Pass

























APPENDIX 2-PHOTOS OF TEST SETUP

Note: See test photos in setup photo document for the actual connections between Product and support equipment.

*****END OF THE REPORT*****