



Tx. Spurious NVNT ax20 5785MHz Ant1 Emission




Date: 1.DEC.2025 18:22:36

Tx. Spurious NVNT ax20 5825MHz Ant1 Emission




Date: 1.DEC.2025 19:23:50


Tx. Spurious NVNT ax40 5755MHz Ant1 Emission




Tx. Spurious NVNT ax40 5795MHz Ant1 Emission




Tx. Spurious NVNT n20 5745MHz Ant1 Emission




Tx. Spurious NVNT n20 5785MHz Ant1 Emission




Tx. Spurious NVNT n20 5825MHz Ant1 Emission



Tx. Spurious NVNT n40 5755MHz Ant1 Emission



Tx. Spurious NVNT n40 5795MHz Ant1 Emission



Date: 1.DEC.2025 16:03:36

5 Test setup photo

5.1 Photo of Radiated Emission test

ADP-60D24:



2102M-120300E:



5.2 Photo of Conducted Emission test

ADP-60D24:



2102M-120300E:



6 Photos of EUT

Please refer to the report A2507177-C05-R01.

7 Model list

D3mini	D2mini	D4mini	D5mini
D6mini	D7mini	D8mini	D9mini
D12mini	D13mini	T2mini	T3mini
T4mini	T5mini	T6mini	T7mini
T8mini	T9mini	T12mini	T13mini
T2	T3	T5	T6
S2	S3	S5	C10
C15	C15KDS	C10KDS	K10
K15	W10	W15	W15L
S10	S15	H5	H8
H10			

-----END OF REPORT-----