


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission


Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Worst Case Position

X-axis



-90 deg.




Y-axis



0 deg.



30 deg.



End of Report