APPENDIX


– Test Setup and EUT photographs –

This report must not be reproduced, except in full, without written permission from Global CS Center.

1. Photograph of Test Setup




[Conducted Disturbance – Front]



[Conducted Disturbance – Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center.




[Radiated Disturbance for Below 1 GHz – Front]




[Radiated Disturbance for Below 1 GHz – Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center.

Form No.: SRA-TRF-46/5



[Radiated Disturbance for Above 1 GHz – Front]



[Radiated Disturbance for Above 1 GHz – Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center.

Form No.: SRA-TRF-46/5