


APPENDIX

– Test Setup and EUT photographs –

1. Photograph of Test Setup


☐ Conducted Disturbance




[Mode 1 - 3 : Front]



[Mode 1 - 3 : Rear]




[Mode 4 : Front]




[Mode 4 : Rear]


☐ Radiated Disturbance for Below 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]



[Mode 2 - 5 : Front]




[Mode 2 - 5 : Rear]




[Mode 6 : Front]



[Mode 6 : Rear]




[Mode 7 : Front]




[Mode 7 : Rear]


☐ Radiated Disturbance for Above 1 GHz



[Mode 1 : Front]




[Mode 1 : Rear]



[Mode 2 - 5 : Front]




[Mode 2 - 5 : Rear]




[Mode 6 : Front]



[Mode 6 : Rear]



[Mode 7 : Front]



[Mode 7 : Rear]