

The image displays the disassembly of the back cover of an HTC One X. On the left is the removed back cover, which is a dark, textured material. On the right is the internal chassis of the phone, showing the battery, camera, and various electronic components. A ruler is placed below the components for scale.







