
APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2

Worst Case Position

ECU
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis
X-axis



Y-axis



Z-axis



Immobilizer
Below 30 MHz
Zaxis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis
X-axis



Y-axis



Z-axis



Worst case position



With key



Without key (Worst)

End of Report