




APPENDIX M: INTERNAL PHOTOGRAPHS




PHOTOGRAPH 12: TOP VIEW WITH COVER REMOVED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002




PHOTOGRAPH 13: BOTTOM VIEW OF ANTENNA IN THE REMOVABLE COVER



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002




PHOTOGRAPH 14: INSIDE VIEW OF REMOVABLE COVE WITHOUT ANTENNA



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002




PHOTOGRAPH 15: TOP VIEW OF ANTENNA



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002




PHOTOGRAPH 16: TOP VIEW WITH COVER REMOVED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002




PHOTOGRAPH 17: TOP VIEW OF MAIN PCB BOARD REMOVED FROM CHASSIS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

RTL Work Order: 2001336
RTL Quote Number: QRTL01-382H
Date of Tests: 1-7-2002 to 1-11-2002



PHOTOGRAPH 18: BOTTOM VIEW OF MAIN PCB BOARD REMOVED FROM CHASSIS