

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission

Below 1 GHz



Photo 1




Photo 2

Radiated Spurious Emission

Above 1 GHz




Photo 3




Photo 4

Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report