
APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission

Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




Pre-check of Worst Case Position


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests
(Except Dwell time test)



Photo 1




Photo 2

Antenna Terminal Conducted Tests
(Dwell time test)




Photo 1




Photo 2

End of Report