




### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**




## **Radiated Spurious Emission**


Front



Rear (below 1GHz)




Rear (above 1GHz)




### Worst Case Position


**X-axis**



**Y-axis**



**Z-axis**



**End of Report**