
APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1



Photo 2

Radiated Spurious Emission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)



Pre-check of Worst Case Position

EUT
X-axis



Y-axis




Z-axis




Antenna
X-axis



Y-axis




Z-axis



Pre-check of Worst Case Position

Antenna cable

100 mm



800 mm



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report