

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 3





Photo 4


Worst Case Position

EUT (Left)


X-axis



Y-axis




Z-axis




EUT (Right)


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report