


6. Photographs of test setup


The following photographs show the arrangement of the worst-case.

6.1. AC Power-line Conducted Emissions Photo(s)

[Normal]




[Demo]




6.2. Antenna-port Conducted Measurements Photo(s)

[Normal]

Maximum Peak Conducted Output Power



Others



[Demo]

Maximum Peak Conducted Output Power





Others




6.3. Radiated Spurious Emissions Photo(s)

[Normal]




[Overview of measurement]

Below 1 GHz





Above 1 GHz





X

< EUT Axis >
Y

Z




[Demo]




[Overview of measurement]



Below 1 GHz




Above 1 GHz



X

< EUT Axis >
Y

Z

End of Test Report