



APPENDIX N: INTERNAL PHOTOGRAPHS




PHOTOGRAPH 12: BATTERY REMOVED FROM RADIO




PHOTOGRAPH 13: CHASSIS WITH SHIELDS




PHOTOGRAPH 14: CHASSIS WITH SHIELDS REMOVED




PHOTOGRAPH 15: RF AND LOGIC BOARD BACK OUT OF CHASSIS




PHOTOGRAPH 16: LOGIC BOARD BOTTOM




PHOTOGRAPH 17: LOGIC BOARD TOP




PHOTOGRAPH 18: RF BOARD BOTTOM




Page 70 of 78



PHOTOGRAPH 20: USER INTERFACE BOARD IN FRONT COVER



PHOTOGRAPH 21: USER INTERFACE BOARD BACK



PHOTOGRAPH 22: USER INTERFACE BOARD FRONT