

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission



Front




Rear (Below 1 GHz)




Rear (Above 1 GHz)

Pre-Check Worst Case Position


**Module
X-axis**




Y-axis




Z-axis




**Antenna
Serial number 1
X-axis**




Y-axis




Z-axis




**Antenna
Serial number 4
X-axis**



Y-axis



Z-axis



End of Report