


APPENDIX 3: Photographs of test setup

Conducted Emission




Radiated Spurious Emission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




Pre-check of Worst Case Position

Module


X-axis



Y-axis



Z-axis




Antenna

X-axis




Y-axis



Z-axis



Antenna Terminal Conducted Tests



End of Report