

APPENDIX 3: Photographs of test setup

Conducted Emission (DC 3.8 V line)




Conducted Emission
(DC 5.0 V line)




Radiated Spurious Emission

Below 1 GHz

Front



Rear



Above 1 GHz

Front




Rear




Pre-check of Worst Case Position


X-axis



Y-axis



Z-axis



End of Report