








11B_Ant1_2412_1000~26500




11B_Ant1_2437_0~Reference









11B_Ant1_2462_1000~26500




11G_Ant1_2412_0~Reference








11G_Ant1_2437_1000~26500




11G_Ant1_2462_0~Reference















APPENDIX A: PHOTOGRAPHS OF TEST SETUP

Radiated Spurious Emissions



Conducted Emissions at AC Power Line (150kHz-30MHz)



APPENDIX B: PHOTOGRAPHS OF EUT

Reference to the test report No. BLA-EMC-202211-A0601

----END OF REPORT----

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.