

APPENDIX 3: Photographs of Test Setup

Conducted Emission





Photo 1



Photo 2


Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)

Pre-Check of Worst Case Position


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report