

APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1



Photo 2


Radiated Spurious Emission



Front




Rear (Below 1 GHz)



Rear (Above 1 GHz)

Pre-check of Worst Case Position

**With controller
X-axis**



Y-axis



Z-axis



**Without controller
X-axis**



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report