




APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

below 1 GHz



above 1 GHz




Pre-check of Worst Case Position


X-axis



Y-axis



Z-axis



End of Report