

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc.

Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1





Photo 2

Worst Case Position
Below 1GHz (Horizontal: with Cradle/ Vertical: with Cradle)
Above 1GHz (Horizontal: Z/ Vertical: Y)

X-axis



with Cradle



Y-axis



Z-axis



End of Report