



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85224-1571

www.goodnet.com/~mflom, (602) 926-3100, FAX: 926-3598

CASTEL0013

F.C.C. RULE: Section 2.975

S T A T E M E N T

This equipment has been tested in accordance with the requirements contained in the appropriate Commission Regulations.

To the best of my knowledge, these tests were performed using measurement procedures consistent with industry or Commission standards, and demonstrate that the equipment complied with the appropriate standards.

Each unit manufactured, imported or marketed, as defined in the Commission's regulations, will conform to the sample tested within the variations that can be expected due to quantity production and testing on a statistical basis.

I further certify that the necessary measurements were made by M. FLOM ASSOCIATES, INC., Suite 107, 3356 North San Marcos Place, Chandler, Arizona 85224.

SUPERVISED BY:


MORTON FLOM, P. Eng.