


APPENDIX 3: Photographs of test setup


Conducted Emission




Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)

Worst Case Position


Module
X-axis



Y-axis



Z-axis



Antenna
X-axis



Y-axis



Z-axis



End of Report