

Photos

Emission tests to FCC and IC requirements of HA03

Performed for Intermatic Inc.

Page 1 of 3

This exhibit is an extract of

DELTA Test Report E501839-1
DANAK-197369
5 March 2004

containing only the photos of the test set-ups

DELTA

Danish Electronics,
Light & Acoustics

Venlighedsvej 4
2970 Hørsholm
Denmark

Tel. (+45) 72 19 40 00
Fax (+45) 72 19 40 01
www.delta.dk





Photo 1 Set-up for conducted emission measurements.
The LISN is bonded to the vertical ground plane (wall) of the screened room.




Photo 2 Set-up for conducted emission measurements.
The LISN is bonded to the vertical ground plane (wall) of the screened room.




Photo 3 Set-up for measurements 30 – 1000 MHz. Date is 2004-02-12. Camera time is faulty.



Photo 4 Measurement set-up > 1 GHz.