


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

Front




Rear (Below 30 MHz)



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Pre-check of Worst Case Position


(EUT)
X-axis



(cable (antenna))
X-axis



Y-axis




Y-axis



Z-axis



Z-axis



Frequency Stability



Photo 1




Photo 2

End of Report